

Vessel - Asphalt Teranga (IMO: 9263942)



Inspection Type 006 - Vessel Inspection Report

Inspection Date 22 May 2024
Inpector Kamlesh Jalori

From Port Marseille
To Port Marseille
Hours Onboard 42 Hrs
Avg Audit Findings 97 %
No of NCRs 0
No of Observation 10



### **Crew Interview & Attendance Record**

Staff Name Rank Remarks

**Auditor Signature** 

Kamlesh Jalori



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.01 - Part I - External Condition

Question 01.01.02 - External Condition - Rudder

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.01 - Part I - External Condition

Question 01.01.03 - External Condition - Ship's name and Port of Registry

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.01 - Part I - External Condition

Question 01.01.04 - External Condition - Hull - Topside area

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.01 - Part I - External Condition

Question 01.01.05 - External Condition - Hull - Boot top area

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.01 - Part I - External Condition

Question 01.01.06 - External Condition - Draft marks

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.01 - Part I - External Condition

Question 01.01.07 - External Condition - Plimsoll mark

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.01 - Part I - External Condition

Question 01.01.08 - External Condition - Bow thruster / Bulb mark / tank marks

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.02 - Decks - Ships name - bridge wings

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.04 - Decks - Railings and Bulwark

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.05 - Decks - Superstructure / Funnel

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.06 - Decks - Forecastle deck plating

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.07 - Decks - Windlass

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.09 - Decks - Mooring ropes and wires

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.10 - Decks - Mooring winches on forecastle deck

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.11 - Decks - Deck Light masts and fittings

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.13 - Decks - Forward and aft Talk back system

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.14 - Decks - Main deck plating

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.15b - Pipelines - Cargo

Answer Detail Grade - No



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.15c - Pipelines - Steam/Thermal Oil

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.15d - Pipelines - Fire

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.15e - Pipelines - Foam

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.15f - Pipelines - Hydraulic

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.16 - Decks - Cargo manifold and drip tray/Various Pressure & Temp. gauges

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.19 - Decks - Mooring winches on main deck

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.20 - Decks - Aft deck / poop deck plating

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.21 - Decks - Mooring winches on aft / poop deck

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.22 - Decks - Condition of spare propeller, anchor

Answer Detail Grade - Yes

Answer Remark Spare anchor on board



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.26a - Tankers - Cargo tank domes

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.26e - Tankers - Level gauging systems

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.26f - Tankers - PV valves / air vents / Mast risers

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.01 - Internal Hull Structure - Fore peak store(s)

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.01 - Cargo Pump Room - Housekeeping and general condition

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.03 - Cargo Pump Room - Stripper pump / Cargo eductors

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.05 - Cargo Pump Room - Pipe lines/Insulations

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.06 - Cargo Pump Room - Bilges

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.11 - Cargo Pump Room - Lighting

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.12 - Cargo Pump Room - Hydraulic and pneumatic valves and pipelines in p/p room

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.05 - Accommodation Spaces - Deck lighting and cable fitting

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.06 - Accommodation Spaces - Railings

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.08 - Accommodation Spaces - Alleyways

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.09 - Accommodation Spaces - Lighting inside alleyways

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.10 - Accommodation Spaces - Galley

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.12 - Accommodation Spaces - Provision rooms

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.14 - Accommodation Spaces - Laundries and dry rooms

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.15 - Accommodation Spaces - Hobby room

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.16 - Accommodation Spaces - Crew Wash rooms

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.17 - Accommodation Spaces - Crew change rooms

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.20 - Accommodation Spaces - Officers Mess room

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.21 - Accommodation Spaces - Officers lounge / smoke room

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.22 - Accommodation Spaces - Crew mess room

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.23 - Accommodation Spaces - Crew lounge / smoke room

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.25 - Accommodation Spaces - Deck office / Cargo control room and its equipments

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.28 - Accommodation Spaces - Store rooms and lockers

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.01 - Navigation Bridge - General maintenance and house keeping

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.02 - Navigation Bridge - Chart room

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.04 - Navigation Bridge - Navigation light masts and fittings

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.05 - Navigation Bridge - Magnetic Compass - standard / gyro and repeaters

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.06 - Navigation Bridge - Auto Pilot

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.07 - Navigation Bridge - Helm indicators - inside wheelhouse and on bridge wings

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.08 - Navigation Bridge - Tachometers - inside wheelhouse and on bridge wings

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.11 - Navigation Bridge - VHF

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.12 - Navigation Bridge - Echo sounder

Answer Detail Grade - Yes
Answer Remark Alarm tried out

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.13 - Navigation Bridge - AIS

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.14 - Navigation Bridge - SSAS

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.15 - Navigation Bridge - BNWAS

Answer Detail Grade - Yes

Answer Remark Alarm tried out,

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.16 - Navigation Bridge - Voyage data recorder

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.17 - Navigation Bridge - Speed log

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.18 - Navigation Bridge - GPS / Satellite Navigator

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.19 - Navigation Bridge - Chronometer

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.20 - Navigation Bridge - Barometer

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.21 - Navigation Bridge - Sextants

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.22 - Navigation Bridge - Binoculars

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.23 - Navigation Bridge - Aldis lamp

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.33 - Navigation Bridge - GMDSS Walkie Talkies

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.35 - Navigation Bridge - GMDSS batteries

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.01 - Engine Room - Housekeeping and general maintenance

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.02a - Engine Room - Main engine - Turbo charger

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.02b - Engine Room - Main engine - Control stand

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.02e - Engine Room - Main engine - Shaft tunnel

Answer Detail

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.02g - Engine Room - Main engine - Crankcase doors

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.02h - Engine Room - Main engine - Under Piston area

Answer Detail

Answer Remark NA



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.02n - Engine Room - Main engine - Alarms and Trips

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.03 - Engine Room - Main S.W pumps

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.05 - Engine Room - Fire pump

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.06 - Engine Room - Bilge pump

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.07 - Engine Room - General Service pump

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.08 - Engine Room - Ballast pump

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.09 - Engine Room - Bilge & floor plates (safety aspects and cleanliness)

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.10 - Engine Room - Fuel oil transfer pump

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.15 - Engine Room - Fridge cooling pump

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.16 - Engine Room - A/C S.W pump

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.21 - Engine Room - H.O Purifier

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.22 - Engine Room - D.O Purifier

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.23 - Engine Room - L.O Purifier

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.24 - Engine Room - Main air compressor

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.26 - Engine Room - Emergency air compressor

Answer Detail Grade - Yes

Answer Remark Main air no 2 is emergency air comp



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.27 - Engine Room - Air bottles, Control air dryers

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.30 - Engine Room - Fuel heater & Lagging on hot fuel pipes

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.32 - Engine Room - Viscometers

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.33 - Engine Room - Hydrophore tanks

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.34d - Engine Room - Aux. Engines - Crankcase doors

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.34e - Engine Room - Aux. Engines - Pressure and Temperature gauges

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.34h - Engine Room - Aux. Engines - Nozzle cooling pump

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.34i - Engine Room - Aux. Engines - Governor

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.34k - Engine Room - Aux. Engines - F.W. / L.O. Coolers

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.34l - Engine Room - Aux. Engines - Floor plates under A/Es clean & oil free?

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.35 - Engine Room - Alternators

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.36 - Engine Room - Motors / starters

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.37 - Engine Room - Main switchboard

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.39 - Engine Room - Cable trays

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.40 - Engine Room - Emergency Generator / Batteries

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.41 - Engine Room - Fridge compressor

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.59 - Engine Room - CO2 room

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.61 - Engine Room - Remote switches and cut-offs

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.64 - Engine Room - Steering flat

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.65 - Engine Room - Storage of chemicals

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.66 - Engine Room - Workshop

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.67 - Engine Room - E/R crane

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.68 - Engine Room - Stores

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 01.08.69 - Engine Room - Spares

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 01.09.01 - Record Keeping - Deck Log Book

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 01.09.02 - Record Keeping - Official Log Book

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 01.09.03 - Record Keeping - Night Order Book

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 01.09.04 - Record Keeping - Movement (Bell) Book

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 01.09.07 - Record Keeping - Chronometer Log

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 01.09.09 - Record Keeping - Radar Log

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 01.09.11 - Record Keeping - Garbage Log

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 01.09.19 - Record Keeping - E/R Log Book

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 01.09.20 - Record Keeping - Oil Record Book

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.10 - Part X - Certificates And Appr

Question 01.10.05 - Certificates and Approvals - Life raft Certificate

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 01.11.01 - Safety Equipment and Alarms - General Alarm

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 01.11.05 - Safety Equipment and Alarms - Fridge room alarm

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 01.11.06 - Safety Equipment and Alarms - E/R Bilge High level alarms

Answer Detail Grade - Yes
Answer Remark Alarm tried out

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 01.11.09 - Safety Equipment and Alarms - Fixed foam system

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 01.11.14 - Safety Equipment and Alarms - Fire mains / hydrants

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 01.11.15 - Safety Equipment and Alarms - Hoses / nozzles

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 01.11.16 - Safety Equipment and Alarms - Pollution Locker and equipments

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 01.11.18 - Safety Equipment and Alarms - Emergency generator

Answer Detail Grade - Yes

Answer Remark Tried out with hydraudralic starting arrangement



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 01.11.20 - Safety Equipment and Alarms - Life boat operation

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 01.11.22 - Safety Equipment and Alarms - Life boat engines

Answer Detail Grade - Yes

Answer Remark Tried out i

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 01.11.27 - Safety Equipment and Alarms - Fireman's outfit with accessories

Answer Detail Grade - Yes



Vessel - Asphalt Teranga (IMO: 9263942)



Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 01.11.28 - Safety Equipment and Alarms - Emergency Towing System

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.12 - Part XII - Environmental

Question 01.12.01 - Environmental - Ballast water management

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.12 - Part XII - Environmental

Question 01.12.02 - Environmental - Garbage management

Answer Detail Grade - Yes