



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Inspection Type 006 - Vessel Inspection Report

Inspection Date 31 Jan 2021

Inspector Kamlesh Jalori

From Port Lome

To Port Lome

Hours Onboard

Avg Audit Findings 65 %

No of NCRs 0

No of observation 0



## Crew Interview & Attendance Record

Staff Name	Rank	Remarks
------------	------	---------

**Auditor Signature**

\_\_\_\_\_  
Kamlesh Jalori



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

## Negative Findings

Defect ID	Chapter	Category	Question	Answer Details	Is Critical	Status	Link
-----------	---------	----------	----------	----------------	-------------	--------	------

## Additional NCRs

Defect ID	NCR No	Observations	Date of Disposition	Status
-----------	--------	--------------	---------------------	--------

## Additional Observations

Defect ID	Observations	Date of Disposition	Status
-----------	--------------	---------------------	--------

## Positive / Neutral Findings

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.01 - External Condition - Propeller	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.02 - External Condition - Rudder	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.03 - External Condition - Ship's name and Port of Registry	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.04 - External Condition - Hull - Topside area	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.05 - External Condition - Hull - Boot top area	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.06 - External Condition - Draft marks	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.07 - External Condition - Plimsoll mark	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.08 - External Condition - Bow thruster / Bulb mark / tank marks	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.01 - Decks - Accommodation Ladders - Platform / Wires / Motor	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.02 - Decks - Ships name - bridge wings	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.03 - Decks - MOT Gangway	Grade - Yes Answer Remark :	No	



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.04 - Decks - Railings and Bulwark	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.05 - Decks - Superstructure / Funnel	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.06 - Decks - Forecastle deck plating	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.07 - Decks - Windlass	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.08 - Decks - Anchor / cables - port and STBD	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.09 - Decks - Mooring ropes and wires	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.10 - Decks - Mooring winches on forecastle deck	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.11 - Decks - Deck Light masts and fittings	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.12 - Decks - Forward mast	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.13 - Decks - Forward and aft Talk back system	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.14 - Decks - Main deck plating	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15a - Pipelines - Ballast	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15b - Pipelines - Cargo	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15c - Pipelines - Steam/Thermal Oil	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15d - Pipelines - Fire	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15e - Pipelines - Foam	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15f - Pipelines - Hydraulic	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15g - Pipelines - Electrical conduit	Grade - Yes Answer Remark : Need maintenance	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15h - Pipelines - Insulation	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.16 - Decks - Cargo manifold and drip tray/Various Pressure & Temp. gauges	Grade - Yes Answer Remark :	No	



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.17 - Decks - Air pipes / Sounding pipes / Filling pipes	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.18 - Decks - Cranes / Derricks and associated loose gear, motors and winches	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.19 - Decks - Mooring winches on main deck	Grade - Yes Answer Remark : Greasing routines	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.20 - Decks - Aft deck / poop deck plating	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.21 - Decks - Mooring winches on aft / poop deck	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.22 - Decks - Condition of spare propeller, anchor	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.23 - Decks - Monkey island deck plating	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.24 - Decks - Main mast and fittings	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.25a - Tugs - Towing winch	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.25b - Tugs - Deck rollers	Grade - Yes Answer Remark : Port fwd roller seized- to free	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.25c - Tugs - Fenders	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.25d - Tugs - Aft control station	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26a - Tankers - Cargo tank domes	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26b - Tankers - Ballast tank openings	Grade - Yes Answer Remark : Man hole doors need maintenance	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26c - Tankers - Deck valves including stub pieces	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26d - Tankers - Ullage ports / vapor locks	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26e - Tankers - Level gauging systems	Grade - Yes Answer Remark : 2S tank high level testing	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26f - Tankers - PV valves / air vents / Mast risers	Grade - Yes Answer Remark :	No	



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26g - Tankers - Deck Seal / PV Breaker on IG line	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.27 - Deck Lighting and Emergency Lighting	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.01 - Internal Hull Structure - Fore peak store(s)	Grade - Yes Answer Remark : Pin hole in scupper line	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.02 - Internal Hull Structure - Paint room including its fixed fire extinguishing system	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.03 - Internal Hull Structure - Fore peak tank	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.04 - Internal Hull Structure - Chain lockers and void spaces	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.05 - Internal Hull Structure - For'd hydraulic room for mooring winches	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.06 - Internal Hull Structure - Cargo tank No 1 C/P/S(includes insulation)	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.07 - Internal Hull Structure - Cargo tank No 2 C/P/S(includes insulation)	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.08 - Internal Hull Structure - Cargo tank No 3 C/P/S(includes insulation)	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.09 - Internal Hull Structure - Cargo tank No 4 C/P/S(includes insulation)	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.10 - Internal Hull Structure - Cargo tank No 5 C/P/S(includes insulation)	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.11 - Internal Hull Structure - Cargo tank No 6 C/P/S(includes insulation)	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.12 - Internal Hull Structure - Cargo tank No 7 C/P/S(includes insulation)	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.13 - Internal Hull Structure - Cargo tank No 8 C/P/S(includes insulation)	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.14 - Internal Hull Structure - Cargo tank No 9 C/P/S(includes insulation)	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.15 - Internal Hull Structure - Water ballast topside tanks	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.16 - Internal Hull Structure - Water ballast D.B. tanks	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.17 - Internal Hull Structure - Slop tanks	Grade - No Answer Remark :	No	



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.18 - Internal Hull Structure - Butterworth machines	Grade - No Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.19 - Internal Hull Structure - COW system	Grade - No Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.20 - Internal Hull Structure - IG system and valves	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.21 - Internal Hull Structure - Deep tanks outside E/R	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.22 - Internal Hull Structure - Cofferdams outside E/R	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.23 - Internal Hull Structure - Pipe tunnel	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.24 - Internal Hull Structure - Aft peak stores	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.25 - Internal Hull Structure - E/R L.O. tanks	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.26 - Internal Hull Structure - E/R D.B. tanks	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.27 - Internal Hull Structure - E/R bunker tanks	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.28 - Internal Hull Structure - Cofferdams inside E/R	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.01 - Mast Houses/ Midship Stores - Internal area	Grade - Yes Answer Remark : Mid ship store needs to be arranged and secured	No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.02 - Mast Houses / Midship Stores - Hydraulic motors		No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.03 - Mast Houses / Midship Stores - Electric panels	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.04 - Mast Houses / Midship Stores - Doors	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.05 - Mast Houses / Midship Stores - Top decks		No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.06 - Mast Houses / Midship Stores - Ladders		No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.07 - Mast Houses / Midship Stores - Fittings		No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.08 - Mast Houses / Midship Stores - House keeping		No	



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.01 - Cargo Pump Room - Housekeeping and general condition	Grade - Yes Answer Remark : Needs cleaning and painting	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.02 - Cargo Pump Room - Cargo pumps / Ballast pumps/Pressure & Temp. gauges	Grade - Yes Answer Remark : Pump suction and discharge pr sensors not working. Pump gland packing needs renwal for pump 1&3	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.03 - Cargo Pump Room - Stripper pump / Cargo eductors	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.04 - Cargo Pump Room - Vacuum stripping system	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.05 - Cargo Pump Room - Pipe lines/Insulations	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.06 - Cargo Pump Room - Bilges	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.07 - Cargo Pump Room - Ventilation/Bottom Flap Operation from outside P/P Room	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.08 - Cargo Pump Room - Ladders, Platforms and gratings	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.09 - Cargo Pump Room - Bilge Alarm(s)	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.10 - Cargo Pump Room - Butterworth heater	Grade - No Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.11 - Cargo Pump Room - Lighting	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.12 - Cargo Pump Room - Hydraulic and pneumatic valves and pipelines in p/p room	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.13 - Cargo Pump Room - Gas detection system	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.01 - Accommodation Spaces - Companionways on open decks		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.02 - Accommodation Spaces - Vent flaps - natural and forced		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.03 - Accommodation Spaces - Accommodation decks		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.04 - Accommodation Spaces - Doors - Watertight / Weather tight		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.05 - Accommodation Spaces - Deck lighting and cable fitting		No	





# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.06 - Accommodation Spaces - Railings		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.07 - Accommodation Spaces - Companionways inside accommodation		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.08 - Accommodation Spaces - Alleyways		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.09 - Accommodation Spaces - Lighting inside alleyways		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.10 - Accommodation Spaces - Galley		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.11 - Accommodation Spaces - Pantries		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.12 - Accommodation Spaces - Provision rooms		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.13 - Accommodation Spaces - Fridge rooms		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.14 - Accommodation Spaces - Laundries and dry rooms		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.15 - Accommodation Spaces - Hobby room		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.16 - Accommodation Spaces - Crew Wash rooms		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.17 - Accommodation Spaces - Crew change rooms		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.18 - Accommodation Spaces - Crew cabins		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.19 - Accommodation Spaces - Officers cabins		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.20 - Accommodation Spaces - Officers Mess room		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.21 - Accommodation Spaces - Officers lounge / smoke room		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.22 - Accommodation Spaces - Crew mess room		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.23 - Accommodation Spaces - Crew lounge / smoke room		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.24 - Accommodation Spaces - Welfare equipment		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.25 - Accommodation Spaces - Deck office / Cargo control room and its equipments		No	





# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.26 - Accommodation Spaces - Conference room		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.27 - Accommodation Spaces - Engineers office		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.28 - Accommodation Spaces - Store rooms and lockers		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.29 - Accommodation Spaces - Cable ducts		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.30 - Accommodation Spaces - Garbage bins		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.01 - Navigation Bridge - General maintenance and house keeping		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.02 - Navigation Bridge - Chart room		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.03 - Navigation Bridge - Battery room		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.04 - Navigation Bridge - Navigation light masts and fittings		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.05 - Navigation Bridge - Magnetic Compass - standard / gyro and repeaters		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.06 - Navigation Bridge - Auto Pilot		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.07 - Navigation Bridge - Helm indicators - inside wheelhouse and on bridge wings		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.08 - Navigation Bridge - Tachometers - inside wheelhouse and on bridge wings		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.09 - Navigation Bridge - Deck IG manometer		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.10 - Navigation Bridge - Radars and ARPA		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.11 - Navigation Bridge - VHF		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.12 - Navigation Bridge - Echo sounder		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.13 - Navigation Bridge - AIS		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.14 - Navigation Bridge - SSAS		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.15 - Navigation Bridge - BNWAS		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.16 - Navigation Bridge - Voyage data recorder		No	



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.17 - Navigation Bridge - Speed log		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.18 - Navigation Bridge - GPS / Satellite Navigator		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.19 - Navigation Bridge - Chronometer		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.20 - Navigation Bridge - Barometer		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.21 - Navigation Bridge - Sextants		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.22 - Navigation Bridge - Binoculars		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.23 - Navigation Bridge - Aldis lamp		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.24 - Navigation Bridge - Flags		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.25 - Navigation Bridge - Charts and status of correction		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.26 - Navigation Bridge - ECDIS		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.27 - Navigation Bridge - Nautical Publications		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.28 - Navigation Bridge - Notices to Mariners		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.29 - Navigation Bridge - Technical Library		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.30 - Navigation Bridge - Radio room		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.31 - Navigation Bridge - Main transmitter / Main Receiver		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.32 - Navigation Bridge - Emergency transmitter / Emergency Receiver		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.33 - Navigation Bridge - GMDSS Walkie Talkies		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.34 - Navigation Bridge - GMDSS VHF DSC (Operation)		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.35 - Navigation Bridge - GMDSS batteries		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.36 - Navigation Bridge - Satcom / GMDSS terminal		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.37 - Navigation Bridge - Computer / UPS / Stabilizer		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.38 - Navigation Bridge - Hospital alarm		No	



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.01 - Engine Room - Housekeeping and general maintenance		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02a - Engine Room - Main engine - Turbo charger		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02b - Engine Room - Main engine - Control stand		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02c - Engine Room - Main engine - Thrust block		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02d - Engine Room - Main engine - Shaft bearings		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02e - Engine Room - Main engine - Shaft tunnel		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02f - Engine Room - Main engine - Turning gear system		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02g - Engine Room - Main engine - Crankcase doors		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02h - Engine Room - Main engine - Under Piston area		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02i - Engine Room - Main engine - Scavenge space		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02j - Engine Room - Main engine - Exhaust manifold		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02k - Engine Room - Main engine - Fuel oil booster pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02l - Engine Room - Main engine - Fuel oil heating system		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02m - Engine Room - Main engine - L.O.pumps		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02n - Engine Room - Main engine - Alarms and Trips		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02o - Engine Room - Main engine - Air cooler manometers		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02p - Engine Room - Main engine - Uptake manometers		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02q - Engine Room - Main engine - Sheathing on HP fuel pipes		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02r - Engine Room - Main engine - Spark arrestors on exh. uptakes		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02s - Engine Room - Main engine - Exh. boiler gas passage drains clear		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02t - Engine Room - Main engine - T/C gas passage drains clear		No	



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.03 - Engine Room - Main S.W pumps		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.04 - Engine Room - Cooling F.W pumps		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.05 - Engine Room - Fire pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.06 - Engine Room - Bilge pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.07 - Engine Room - General Service pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.08 - Engine Room - Ballast pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.09 - Engine Room - Bilge & floor plates (safety aspects and cleanliness)		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.10 - Engine Room - Fuel oil transfer pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.11 - Engine Room - L.O transfer pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.12 - Engine Room - Sludge pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.13 - Engine Room - Domestic F.W pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.14 - Engine Room - Sanitary water pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.15 - Engine Room - Fridge cooling pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.16 - Engine Room - A/C S.W pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.17 - Engine Room - Harbor service pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.18 - Engine Room - All S.W. valves		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.19 - Engine Room - Tank top		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.20 - Engine Room - Piping - general and in bilge areas		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.21 - Engine Room - H.O Purifier		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.22 - Engine Room - D.O Purifier		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.23 - Engine Room - L.O Purifier		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.24 - Engine Room - Main air compressor		No	



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.25 - Engine Room - Top up compressor		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.26 - Engine Room - Emergency air compressor		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.27 - Engine Room - Air bottles, Control air dryers		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.28 - Engine Room - M/E coolers		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.29 - Engine Room - A/E coolers		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.30 - Engine Room - Fuel heater & Lagging on hot fuel pipes		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.31 - Engine Room - Metal sheathing on H.P fuel pipes		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.32 - Engine Room - Viscometers		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.33 - Engine Room - Hydrophore tanks		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34a - Engine Room - Aux. Engines - General condition and maintenance		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34b - Engine Room - Aux. Engines - Turbo charger		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34c - Engine Room - Aux. Engines - Alarms and trips		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34d - Engine Room - Aux. Engines - Crankcase doors		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34e - Engine Room - Aux. Engines - Pressure and Temperature gauges		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34f - Engine Room - Aux. Engines - Nozzle cooling pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34g - Engine Room - Aux. Engines - Attached F.W. pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34h - Engine Room - Aux. Engines - Nozzle cooling pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34i - Engine Room - Aux. Engines - Governor		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34j - Engine Room - Aux. Engines - Exh. pipe lagging / metal sheathing		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34k - Engine Room - Aux. Engines - F.W. / L.O. Coolers		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34l - Engine Room - Aux. Engines - Floor plates under A/Es clean & oil free?		No	



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34m - Engine Room - Aux. Engines - m. Deck-head & pipes / cables above A/Es clean and oil free?		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34n - Engine Room - Aux. Engines - n. Auto temperature controllers L.O. / F.W. temp		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.35 - Engine Room - Alternators		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.36 - Engine Room - Motors / starters		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.37 - Engine Room - Main switchboard		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.38 - Engine Room - Emergency switchboard		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.39 - Engine Room - Cable trays		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.40 - Engine Room - Emergency Generator / Batteries		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.41 - Engine Room - Fridge compressor		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.42 - Engine Room - Condensers / coolers		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.43 - Engine Room - Thermostatic valves		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.44 - Engine Room - Coils / fans		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.45 - Engine Room - E/R blowers		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.46 - Engine Room - Engine Control Room		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.47 - Engine Room - F.W generator		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.48 - Engine Room - Oily water separator		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.49 - Engine Room - Sewage Plant		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.50 - Engine Room - Incinerator		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51a - Engine Room - Boilers (steam and thermal oil) - Condition and general maintenance		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51b - Engine Room - Boilers (steam and thermal oil) - Feed water pumps		No	



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51c - Engine Room - Boilers (steam and thermal oil) - Circulation pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51d - Engine Room - Boilers (steam and thermal oil) - Safety valve		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51e - Engine Room - Boilers (steam and thermal oil) - Gauge glass		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51f - Engine Room - Boilers (steam and thermal oil) - Automatic Combustion. C		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51g - Engine Room - Boilers (steam and thermal oil) - F.D. fan		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51h - Engine Room - Boilers (steam and thermal oil) - Boiler uptake lagging		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51i - Engine Room - Boilers (steam and thermal oil) - All temperature and pressure gauges		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51j - Engine Room - Boilers (steam and thermal oil) - F.O. pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51k - Engine Room - Boilers (steam and thermal oil) - F.O. heater		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51l - Engine Room - Boilers (steam and thermal oil) - Lagging on hot fuel oil and Heating steam pipes		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51m - Engine Room - Boilers (steam and thermal oil) - Steam dump valve and other steam valves		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51n - Engine Room - Boilers (steam and thermal oil) - Warning notices and operating instructions		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52a - Engine Room - IG system - IG generator		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52b - Engine Room - IG system - IG control panel and control system		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52c - Engine Room - IG system - Pneumatic system		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52d - Engine Room - IG system - IG blower		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52e - Engine Room - IG system - Scrubber unit		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52f - Engine Room - IG system - Oxygen analyzer		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.53 - Engine Room - Soot blower		No	





# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.54 - Engine Room - Exhaust boiler		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55a - Engine Room - COP turbines - Condition and general maintenance		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55b - Engine Room - COP turbines - Alarms and trips		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55c - Engine Room - COP turbines - governor		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55d - Engine Room - COP turbines - L.O. pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55e - Engine Room - COP turbines - L.O. cooler		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55f - Engine Room - COP turbines - Control panel		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55g - Engine Room - COP turbines - Tachometer		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55h - Engine Room - COP turbines - Local temp and pressure gauges		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.56 - Engine Room - Vacuum condenser		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.57 - Engine Room - Condenser S.W. pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.58 - Engine Room - Hot well		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.59 - Engine Room - CO2 room		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.60 - Engine Room - Quick closing valves		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.61 - Engine Room - Remote switches and cut-offs		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.62 - Engine Room - Sky light		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.63 - Engine Room - Blower flaps		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.64 - Engine Room - Steering flat		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.65 - Engine Room - Storage of chemicals		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.66 - Engine Room - Workshop		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.67 - Engine Room - E/R crane		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.68 - Engine Room - Stores		No	



## Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.69 - Engine Room - Spares		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.70 - Engine Room - Tools / instruments		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.71 - Engine Room - LO and water treatment test kits		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.01 - Record Keeping - Deck Log Book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.02 - Record Keeping - Official Log Book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.03 - Record Keeping - Night Order Book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.04 - Record Keeping - Movement (Bell) Book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.05 - Record Keeping - Sounding Book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.06 - Record Keeping - Compass error Book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.07 - Record Keeping - Chronometer Log		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.08 - Record Keeping - Radio Log		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.09 - Record Keeping - Radar Log		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.10 - Record Keeping - Chart correction folio		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.11 - Record Keeping - Garbage Log		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.12 - Record Keeping - Videotel / Training Log		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.13 - Record Keeping - Calibration Log		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.14 - Record Keeping - Stores inventory (deck and saloon)		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.15 - Record Keeping - Spare Part Inventory (Deck)		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.16 - Record Keeping - Planned Maintenance Records(Deck, Radio, Safety Equipment)		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.17 - Record Keeping - Masters Filing System		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.18 - Record Keeping - Chief Engineers Filing System		No	



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.19 - Record Keeping - E/R Log Book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.20 - Record Keeping - Oil Record Book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.21 - Record Keeping - E/R tank sounding book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.22 - Record Keeping - Survey records / Quarterly listing		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.23 - Record Keeping - Spare Part Inventory (E/R)		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.24 - Record Keeping - Planned Maintenance Records (Main, Aux. and Electrical machinery)		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.25 - Record Keeping - Ships drawings and manuals		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.26 - Record Keeping - Ship Security Records		No	
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And Approvals	10.10.01 - Certificates and Approvals - Statutory certificates as per Form D-13		No	
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And Approvals	10.10.02 - Certificates and Approvals - Type approval Certificates for L/Jackets, L/Buoys, Pyrotechnics, Navigation Lights, Sound Signal equipment, shapes, fireman's outfits, fire detection system, alarms, ODME, ODMCS, Sewage plant		No	
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And Approvals	10.10.03 - Certificates and Approvals - Wires and Ropes Test Certificates		No	
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And Approvals	10.10.04 - Certificates and Approvals - Chain Register		No	
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And Approvals	10.10.05 - Certificates and Approvals - Life raft Certificate		No	
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And Approvals	10.10.06 - Certificates and Approvals - Administration approved LSA, LSS and FFA plans		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.01 - Safety Equipment and Alarms - General Alarm		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.02 - Safety Equipment and Alarms - Fire detection system (Accommodation/E.R/Cargo holds)		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.03 - Safety Equipment and Alarms - Hospital Bell		No	



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.04 - Safety Equipment and Alarms - Medical locker / equipment		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.05 - Safety Equipment and Alarms - Fridge room alarm		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.06 - Safety Equipment and Alarms - E/R Bilge High level alarms		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.07 - Safety Equipment and Alarms - CO2 / Halon release alarm		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.08 - Safety Equipment and Alarms - Vent fans flaps / funnel flaps / Remote closing flaps		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.09 - Safety Equipment and Alarms - Fixed foam system		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.10 - Safety Equipment and Alarms - Portable foam system		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.11 - Safety Equipment and Alarms - Steam smothering		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.12 - Safety Equipment and Alarms - Inert gas system		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.13 - Safety Equipment and Alarms - Sprinkler system		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.14 - Safety Equipment and Alarms - Fire mains / hydrants		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.15 - Safety Equipment and Alarms - Hoses / nozzles		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.16 - Safety Equipment and Alarms - Pollution Locker and equipments		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.17 - Safety Equipment and Alarms - Emergency fire pump		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.18 - Safety Equipment and Alarms - Emergency generator		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.19 - Safety Equipment and Alarms - Emergency lights		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.20 - Safety Equipment and Alarms - Life boat operation		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.21 - Safety Equipment and Alarms - Life boat equipment		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.22 - Safety Equipment and Alarms - Life boat engines		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.23 - Safety Equipment and Alarms - Extinguishers - Foam, Water, DCP, CO2		No	



# Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.24 - Safety Equipment and Alarms - Tankscope, Explosimeter, O2 analyzer and Toxic gas detector		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.25 - Safety Equipment and Alarms - Breathalyzer		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.26 - Safety Equipment and Alarms - CABA, Resuscitation equipment		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.27 - Safety Equipment and Alarms - Fireman's outfit with accessories		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.28 - Safety Equipment and Alarms - Emergency Towing System		No	
01.00 - Area/Item Inspected	01.12 - Part XII - Environmental	10.12.01 - Environmental - Ballast water management		No	
01.00 - Area/Item Inspected	01.12 - Part XII - Environmental	10.12.02 - Environmental - Garbage management		No	
01.00 - Area/Item Inspected	01.12 - Part XII - Environmental	10.12.03 - Environmental - Ship Energy efficiency plan		No	
01.00 - Area/Item Inspected	01.12 - Part XII - Environmental	10.12.04 - Environmental - Safety Meeting conducted with entire crew by Superintendent		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.01 - Security - Ship Security Records		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.02 - Security - Security Equipments		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.03 - Security - Security Communications and SSAS		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.04 - Security - Vessel Hardening		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.05 - Security - Security Charts, Publications and Guidance		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.06 - Security - Cyber Security incl. Access to IT/OT Terminals, Workstation Security etc.		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.07 - Security - Cyber Response Plan		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.08 - Security - Personal Devices usage		No	