



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Inspection Type 006 - Vessel Inspection Report

Inspection Date 31 Jul 2021

Inspector Vikram Puri

From Port Agioi Theodoroi

To Port Agioi Theodoroi

Hours Onboard

Avg Audit Findings 55 %

No of NCRs 1

No of observation 17



Crew Interview & Attendance Record

Staff Name	Rank	Remarks
------------	------	---------

Auditor Signature

Vikram Puri



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Negative Findings

Defect ID	Chapter	Category	Question	Answer Details	Is Critical	Status	Link
-----------	---------	----------	----------	----------------	-------------	--------	------

Additional NCRs

Defect ID	NCR No	Observations	Date of Disposition	Status
145	10/2021	Unused-/ non operational water fountains in accommodation to be removed	15 Sep 2021	Completed

Additional Observations

Defect ID	Observations	Date of Disposition	Status
133	Draft and plimsoll marks are either in poor condition or non existent	21 Sep 2021	Completed
134	Aft deck are in bad condition due to water carry over from scrubber.	08 Oct 2021	Completed
135	Monkey island -cosmetic maintenance necessary	20 Sep 2021	Completed
136	COT HHLA Malfunctioning	09 Oct 2021	Completed
137	Hydraulic pipe line showing signs of localised rusting same to be treated and entire length of hydraulic piping to wrap with DENSO tape	14 Oct 2021	Completed
138	Paint room house keeping to improve	09 Sep 2021	Completed
139	Crew changing lockers very untidy- need housekeeping	08 Sep 2021	Completed
140	Sheathing on HP Fuel pipes damaged in number of locations.	21 Sep 2021	Completed
141	Few SW valves are not holding	21 Sep 2021	Completed
142	Boiler- Thermal oil & steam- lagging on hot fuel oil and steam pipes damaged at various locations	08 Sep 2021	Completed
143	Steam dump condenser- frequent chocking of tubes.	21 Sep 2021	Completed
144	Marking of pipe line on deck	06 Sep 2021	Completed
146	Air ducting in boiler room corroded.	08 Oct 2021	Completed
147	Fire wire storage drum and frame to be painted black	14 Oct 2021	Completed
148	Cargo Hose rest on ship side - to paint black	31 Aug 2021	Completed
149	Life boat propeller and aft keel fixture- needs maintenance.	14 Oct 2021	Completed
150	Soot collection tank is in poor condition- maintenance required	09 Sep 2021	Completed



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Positive / Neutral Findings

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.01 - External Condition - Propeller	Grade - No Answer Remark : Not Inspected	No	
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.02 - External Condition - Rudder	Grade - No Answer Remark : Not inspected	No	
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.03 - External Condition - Ship's name and Port of Registry	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.04 - External Condition - Hull - Topside area	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.05 - External Condition - Hull - Boot top area	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.06 - External Condition - Draft marks	Grade - No Answer Remark : Draft marks are in poor rusted condition or non existent	No	
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.07 - External Condition - Plimsoll mark	Grade - No Answer Remark : Plimsoll marks are in poor rusted condition or non existent	No	
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.08 - External Condition - Bow thruster / Bulb mark / tank marks	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.01 - Decks - Accommodation Ladders - Platform / Wires / Motor	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.02 - Decks - Ships name - bridge wings	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.03 - Decks - MOT Gangway	Grade - No Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.04 - Decks - Railings and Bulwark	Grade - Yes Answer Remark : NA	No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.05 - Decks - Superstructure / Funnel	Grade - No Answer Remark : Due to water carry over from scrubber ,aft decks are in bad condition	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.06 - Decks - Forecastle deck plating	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.07 - Decks - Windlass	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.08 - Decks - Anchor / cables - port and STBD		No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.09 - Decks - Mooring ropes and wires	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.10 - Decks - Mooring winches on forecastle deck	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.11 - Decks - Deck Light masts and fittings	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.12 - Decks - Forward mast	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.13 - Decks - Forward and aft Talk back system		No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.14 - Decks - Main deck plating	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15a - Pipelines - Ballast		No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15b - Pipelines - Cargo		No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15c - Pipelines - Steam/Thermal Oil		No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15d - Pipelines - Fire	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15e - Pipelines - Foam	Grade - Yes Answer Remark : NA	No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15f - Pipelines - Hydraulic	Grade - No Answer Remark : Pipes showing signs of localised rusting, same to be treated and entire length of hyd piping to wrap with denso tape.	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15g - Pipelines - Electrical conduit	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15h - Pipelines - Insulation	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.16 - Decks - Cargo manifold and drip tray/Various Pressure & Temp. gauges	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.17 - Decks - Air pipes / Sounding pipes / Filling pipes	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.18 - Decks - Cranes / Derricks and associated loose gear, motors and winches	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.19 - Decks - Mooring winches on main deck	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.20 - Decks - Aft deck / poop deck plating	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.21 - Decks - Mooring winches on aft / poop deck	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.22 - Decks - Condition of spare propeller, anchor		No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.23 - Decks - Monkey island deck plating	Grade - No Answer Remark : Cosmetic maintenance required	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.24 - Decks - Main mast and fittings	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.25a - Tugs - Towing winch		No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.25b - Tugs - Deck rollers		No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.25c - Tugs - Fenders		No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.25d - Tugs - Aft control station		No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26a - Tankers - Cargo tank domes	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26b - Tankers - Ballast tank openings	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26c - Tankers - Deck valves including stub pieces	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26d - Tankers - Ullage ports / vapor locks	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26e - Tankers - Level gauging systems	Grade - No Answer Remark : COT HHLA -Malfunctioning	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26f - Tankers - PV valves / air vents / Mast risers	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26g - Tankers - Deck Seal / PV Breaker on IG line	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.27 - Deck Lighting and Emergency Lighting		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.01 - Internal Hull Structure - Fore peak store(s)	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.02 - Internal Hull Structure - Paint room including its fixed fire extinguishing system	Grade - No Answer Remark : House keeping to improve	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.03 - Internal Hull Structure - Fore peak tank		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.04 - Internal Hull Structure - Chain lockers and void spaces		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.05 - Internal Hull Structure - For'd hydraulic room for mooring winches		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.06 - Internal Hull Structure - Cargo tank No 1 C/P/S(includes insulation)		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.07 - Internal Hull Structure - Cargo tank No 2 C/P/S(includes insulation)		No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.08 - Internal Hull Structure - Cargo tank No 3 C/P/S(includes insulation)		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.09 - Internal Hull Structure - Cargo tank No 4 C/P/S(includes insulation)		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.10 - Internal Hull Structure - Cargo tank No 5 C/P/S(includes insulation)		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.11 - Internal Hull Structure - Cargo tank No 6 C/P/S(includes insulation)		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.12 - Internal Hull Structure - Cargo tank No 7 C/P/S(includes insulation)		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.13 - Internal Hull Structure - Cargo tank No 8 C/P/S(includes insulation)		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.14 - Internal Hull Structure - Cargo tank No 9 C/P/S(includes insulation)		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.15 - Internal Hull Structure - Water ballast topside tanks		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.16 - Internal Hull Structure - Water ballast D.B. tanks		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.17 - Internal Hull Structure - Slop tanks		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.18 - Internal Hull Structure - Butterworth machines		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.19 - Internal Hull Structure - COW system		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.20 - Internal Hull Structure - IG system and valves		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.21 - Internal Hull Structure - Deep tanks outside E/R		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.22 - Internal Hull Structure - Cofferdams outside E/R		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.23 - Internal Hull Structure - Pipe tunnel		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.24 - Internal Hull Structure - Aft peak stores	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.25 - Internal Hull Structure - E/R L.O. tanks		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.26 - Internal Hull Structure - E/R D.B. tanks		No	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.27 - Internal Hull Structure - E/R bunker tanks		No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.28 - Internal Hull Structure - Cofferdams inside E/R		No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.01 - Mast Houses/ Midship Stores - Internal area	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.02 - Mast Houses / Midship Stores - Hydraulic motors		No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.03 - Mast Houses / Midship Stores - Electric panels		No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.04 - Mast Houses / Midship Stores - Doors	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.05 - Mast Houses / Midship Stores - Top decks	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.06 - Mast Houses / Midship Stores - Ladders	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.07 - Mast Houses / Midship Stores - Fittings	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.04 - Part IV - Mast Houses / Midship Stores	01.04.08 - Mast Houses / Midship Stores - House keeping	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.01 - Cargo Pump Room - Housekeeping and general condition	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.02 - Cargo Pump Room - Cargo pumps / Ballast pumps/Pressure & Temp. gauges	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.03 - Cargo Pump Room - Stripper pump / Cargo eductors		No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.04 - Cargo Pump Room - Vacuum stripping system		No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.05 - Cargo Pump Room - Pipe lines/Insulations	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.06 - Cargo Pump Room - Bilges	Grade - Yes Answer Remark : NA	No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.07 - Cargo Pump Room - Ventilation/Bottom Flap Operation from outside P/P Room		No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.08 - Cargo Pump Room - Ladders, Platforms and gratings	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.09 - Cargo Pump Room - Bilge Alarm(s)		No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.10 - Cargo Pump Room - Butterworth heater		No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.11 - Cargo Pump Room - Lighting	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.12 - Cargo Pump Room - Hydraulic and pneumatic valves and pipelines in p/p room	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.13 - Cargo Pump Room - Gas detection system	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.01 - Accommodation Spaces - Companionways on open decks	Grade - No Answer Remark : Due to water carryover from scrubber aft deck are in bad condition	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.02 - Accommodation Spaces - Vent flaps - natural and forced	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.03 - Accommodation Spaces - Accommodation decks		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.04 - Accommodation Spaces - Doors - Watertight / Weather tight	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.05 - Accommodation Spaces - Deck lighting and cable fitting	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.06 - Accommodation Spaces - Railings	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.07 - Accommodation Spaces - Companionways inside accommodation	Grade - Yes Answer Remark : NA	No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.08 - Accommodation Spaces - Alleyways	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.09 - Accommodation Spaces - Lighting inside alleyways	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.10 - Accommodation Spaces - Galley	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.11 - Accommodation Spaces - Pantries	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.12 - Accommodation Spaces - Provision rooms		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.13 - Accommodation Spaces - Fridge rooms		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.14 - Accommodation Spaces - Laundries and dry rooms	Grade - No Answer Remark : Very untidy- housekeeping required	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.15 - Accommodation Spaces - Hobby room		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.16 - Accommodation Spaces - Crew Wash rooms	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.17 - Accommodation Spaces - Crew change rooms	Grade - No Answer Remark : Very untidy-housekeeping required	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.18 - Accommodation Spaces - Crew cabins	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.19 - Accommodation Spaces - Officers cabins	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.20 - Accommodation Spaces - Officers Mess room	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.21 - Accommodation Spaces - Officers lounge / smoke room	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.22 - Accommodation Spaces - Crew mess room	Grade - Yes Answer Remark : NA	No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.23 - Accommodation Spaces - Crew lounge / smoke room	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.24 - Accommodation Spaces - Welfare equipment	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.25 - Accommodation Spaces - Deck office / Cargo control room and its equipments	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.26 - Accommodation Spaces - Conference room	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.27 - Accommodation Spaces - Engineers office		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.28 - Accommodation Spaces - Store rooms and lockers		No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.29 - Accommodation Spaces - Cable ducts	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.30 - Accommodation Spaces - Garbage bins	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.01 - Navigation Bridge - General maintenance and house keeping	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.02 - Navigation Bridge - Chart room	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.03 - Navigation Bridge - Battery room	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.04 - Navigation Bridge - Navigation light masts and fittings	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.05 - Navigation Bridge - Magnetic Compass - standard / gyro and repeaters	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.06 - Navigation Bridge - Auto Pilot	Grade - Yes Answer Remark : NA	No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.07 - Navigation Bridge - Helm indicators - inside wheelhouse and on bridge wings	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.08 - Navigation Bridge - Tachometers - inside wheelhouse and on bridge wings	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.09 - Navigation Bridge - Deck IG manometer		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.10 - Navigation Bridge - Radars and ARPA	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.11 - Navigation Bridge - VHF	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.12 - Navigation Bridge - Echo sounder	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.13 - Navigation Bridge - AIS	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.14 - Navigation Bridge - SSAS	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.15 - Navigation Bridge - BNWAS	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.16 - Navigation Bridge - Voyage data recorder	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.17 - Navigation Bridge - Speed log	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.18 - Navigation Bridge - GPS / Satellite Navigator	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.19 - Navigation Bridge - Chronometer	Grade - No Answer Remark : Not Inspected	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.20 - Navigation Bridge - Barometer		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.21 - Navigation Bridge - Sextants		No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.22 - Navigation Bridge - Binoculars		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.23 - Navigation Bridge - Aldis lamp		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.24 - Navigation Bridge - Flags		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.25 - Navigation Bridge - Charts and status of correction		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.26 - Navigation Bridge - ECDIS	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.27 - Navigation Bridge - Nautical Publications		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.28 - Navigation Bridge - Notices to Mariners		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.29 - Navigation Bridge - Technical Library		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.30 - Navigation Bridge - Radio room	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.31 - Navigation Bridge - Main transmitter / Main Receiver	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.32 - Navigation Bridge - Emergency transmitter / Emergency Receiver	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.33 - Navigation Bridge - GMDSS Walkie Talkies	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.34 - Navigation Bridge - GMDSS VHF DSC (Operation)	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.35 - Navigation Bridge - GMDSS batteries	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.36 - Navigation Bridge - Satcom / GMDSS terminal		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.37 - Navigation Bridge - Computer / UPS / Stabilizer		No	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.38 - Navigation Bridge - Hospital alarm		No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.01 - Engine Room - Housekeeping and general maintenance	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02a - Engine Room - Main engine - Turbo charger	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02b - Engine Room - Main engine - Control stand	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02c - Engine Room - Main engine - Thrust block		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02d - Engine Room - Main engine - Shaft bearings		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02e - Engine Room - Main engine - Shaft tunnel		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02f - Engine Room - Main engine - Turning gear system		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02g - Engine Room - Main engine - Crankcase doors	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02h - Engine Room - Main engine - Under Piston area		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02i - Engine Room - Main engine - Scavenge space		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02j - Engine Room - Main engine - Exhaust manifold		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02k - Engine Room - Main engine - Fuel oil booster pump	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02l - Engine Room - Main engine - Fuel oil heating system	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02m - Engine Room - Main engine - L.O.pumps	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02n - Engine Room - Main engine - Alarms and Trips		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02o - Engine Room - Main engine - Air cooler manometers		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02p - Engine Room - Main engine - Uptake manometers		No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02q - Engine Room - Main engine - Sheathing on HP fuel pipes	Grade - No Answer Remark : Sheathing damaged at various locations	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02s - Engine Room - Main engine - Exh. boiler gas passage drains clear		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02t - Engine Room - Main engine - T/C gas passage drains clear		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.03 - Engine Room - Main S.W pumps	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.04 - Engine Room - Cooling F.W pumps	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.05 - Engine Room - Fire pump	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.06 - Engine Room - Bilge pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.07 - Engine Room - General Service pump	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.08 - Engine Room - Ballast pump	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.09 - Engine Room - Bilge & floor plates (safety aspects and cleanliness)	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.10 - Engine Room - Fuel oil transfer pump	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.11 - Engine Room - L.O transfer pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.12 - Engine Room - Sludge pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.13 - Engine Room - Domestic F.W pump	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.14 - Engine Room - Sanitary water pump	Grade - Yes Answer Remark : NA	No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.15 - Engine Room - Fridge cooling pump	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.16 - Engine Room - A/C S.W pump	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.17 - Engine Room - Harbor service pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.18 - Engine Room - All S.W. valves	Grade - No Answer Remark : Few SW valves not holding	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.19 - Engine Room - Tank top	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.20 - Engine Room - Piping - general and in bilge areas	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.21 - Engine Room - H.O Purifier	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.22 - Engine Room - D.O Purifier	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.23 - Engine Room - L.O Purifier	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.24 - Engine Room - Main air compressor	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.25 - Engine Room - Top up compressor	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.26 - Engine Room - Emergency air compressor	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.27 - Engine Room - Air bottles, Control air dryers	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.28 - Engine Room - M/E coolers	Grade - Yes Answer Remark : NA	No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.29 - Engine Room - A/E coolers		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.30 - Engine Room - Fuel heater & Lagging on hot fuel pipes	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.31 - Engine Room - Metal sheathing on H.P fuel pipes	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.32 - Engine Room - Viscometers	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.33 - Engine Room - Hydrophore tanks	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34a - Engine Room - Aux. Engines - General condition and maintenance	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34b - Engine Room - Aux. Engines - Turbo charger	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34c - Engine Room - Aux. Engines - Alarms and trips		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34d - Engine Room - Aux. Engines - Crankcase doors	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34e - Engine Room - Aux. Engines - Pressure and Temperature gauges		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34f - Engine Room - Aux. Engines - Nozzle cooling pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34g - Engine Room - Aux. Engines - Attached F.W. pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34h - Engine Room - Aux. Engines - Nozzle cooling pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34i - Engine Room - Aux. Engines - Governor		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34j - Engine Room - Aux. Engines - Exh. pipe lagging / metal sheathing	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34k - Engine Room - Aux. Engines - F.W. / L.O. Coolers	Grade - Yes Answer Remark : NA	No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34l - Engine Room - Aux. Engines - Floor plates under A/Es clean & oil free?	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34m - Engine Room - Aux. Engines - m. Deck-head & pipes / cables above A/Es clean and oil free?	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34n - Engine Room - Aux. Engines - n. Auto temperature controllers L.O. / F.W. temp		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.35 - Engine Room - Alternators	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.36 - Engine Room - Motors / starters	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.37 - Engine Room - Main switchboard	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.38 - Engine Room - Emergency switchboard	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.39 - Engine Room - Cable trays	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.40 - Engine Room - Emergency Generator / Batteries		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.41 - Engine Room - Fridge compressor	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.42 - Engine Room - Condensers / coolers	Grade - No Answer Remark : Steam condensor/dump condenser tubes reported to be chocking.	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.43 - Engine Room - Thermostatic valves		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.44 - Engine Room - Coils / fans		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.45 - Engine Room - E/R blowers		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.46 - Engine Room - Engine Control Room	Grade - Yes Answer Remark : NA	No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.47 - Engine Room - F.W generator	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.48 - Engine Room - Oily water separator	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.49 - Engine Room - Sewage Plant	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.50 - Engine Room - Incinerator	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51a - Engine Room - Boilers (steam and thermal oil) - Condition and general maintenance	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51b - Engine Room - Boilers (steam and thermal oil) - Feed water pumps	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51c - Engine Room - Boilers (steam and thermal oil) - Circulation pump	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51d - Engine Room - Boilers (steam and thermal oil) - Safety valve	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51e - Engine Room - Boilers (steam and thermal oil) - Gauge glass	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51f - Engine Room - Boilers (steam and thermal oil) - Automatic Combustion. C	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51g - Engine Room - Boilers (steam and thermal oil) - F.D. fan	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51h - Engine Room - Boilers (steam and thermal oil) - Boiler uptake lagging	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51i - Engine Room - Boilers (steam and thermal oil) - All temperature and pressure gauges	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51j - Engine Room - Boilers (steam and thermal oil) - F.O. pump	Grade - Yes Answer Remark : NA	No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51k - Engine Room - Boilers (steam and thermal oil) - F.O. heater	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51l - Engine Room - Boilers (steam and thermal oil) - Lagging on hot fuel oil and Heating steam pipes	Grade - No Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51m - Engine Room - Boilers (steam and thermal oil) - Steam dump valve and other steam valves	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51n - Engine Room - Boilers (steam and thermal oil) - Warning notices and operating instructions	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52a - Engine Room - IG system - IG generator		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52b - Engine Room - IG system - IG control panel and control system		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52c - Engine Room - IG system - Pneumatic system		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52d - Engine Room - IG system - IG blower		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52e - Engine Room - IG system - Scrubber unit		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52f - Engine Room - IG system - Oxygen analyzer		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.53 - Engine Room - Soot blower		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.54 - Engine Room - Exhaust boiler	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55a - Engine Room - COP turbines - Condition and general maintenance		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55b - Engine Room - COP turbines - Alarms and trips		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55c - Engine Room - COP turbines - governor		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55d - Engine Room - COP turbines - L.O. pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55e - Engine Room - COP turbines - L.O. cooler		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55f - Engine Room - COP turbines - Control panel		No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55g - Engine Room - COP turbines - Tachometer		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55h - Engine Room - COP turbines - Local temp and pressure gauges		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.56 - Engine Room - Vacuum condenser		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.57 - Engine Room - Condenser S.W. pump		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.58 - Engine Room - Hot well	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.59 - Engine Room - CO2 room	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.60 - Engine Room - Quick closing valves		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.61 - Engine Room - Remote switches and cut-offs		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.62 - Engine Room - Sky light	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.63 - Engine Room - Blower flaps		No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.64 - Engine Room - Steering flat	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.65 - Engine Room - Storage of chemicals	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.66 - Engine Room - Workshop	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.67 - Engine Room - E/R crane	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.68 - Engine Room - Stores	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.69 - Engine Room - Spares	Grade - Yes Answer Remark : NA	No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.70 - Engine Room - Tools / instruments	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.71 - Engine Room - LO and water treatment test kits	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.01 - Record Keeping - Deck Log Book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.02 - Record Keeping - Official Log Book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.03 - Record Keeping - Night Order Book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.04 - Record Keeping - Movement (Bell) Book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.05 - Record Keeping - Sounding Book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.06 - Record Keeping - Compass error Book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.07 - Record Keeping - Chronometer Log		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.08 - Record Keeping - Radio Log		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.09 - Record Keeping - Radar Log		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.10 - Record Keeping - Chart correction folio		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.11 - Record Keeping - Garbage Log		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.12 - Record Keeping - Videotel / Training Log		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.13 - Record Keeping - Calibration Log		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.14 - Record Keeping - Stores inventory (deck and saloon)		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.15 - Record Keeping - Spare Part Inventory (Deck)		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.16 - Record Keeping - Planned Maintenance Records(Deck, Radio, Safety Equipment)		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.17 - Record Keeping - Masters Filing System		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.18 - Record Keeping - Chief Engineers Filing System		No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.19 - Record Keeping - E/R Log Book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.20 - Record Keeping - Oil Record Book	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.21 - Record Keeping - E/R tank sounding book		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.22 - Record Keeping - Survey records / Quarterly listing	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.23 - Record Keeping - Spare Part Inventory (E/R)		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.24 - Record Keeping - Planned Maintenance Records (Main, Aux. and Electrical machinery)		No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.25 - Record Keeping - Ships drawings and manuals		No	
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And Approvals	10.10.01 - Certificates and Approvals - Statutory certificates as per Form D-13		No	
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And Approvals	10.10.02 - Certificates and Approvals - Type approval Certificates for L/Jackets, L/Buoys, Pyrotechnics, Navigation Lights, Sound Signal equipment, shapes, fireman's outfits, fire detection system, alarms, ODME, ODMCS, Sewage plant		No	
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And Approvals	10.10.03 - Certificates and Approvals - Wires and Ropes Test Certificates		No	
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And Approvals	10.10.04 - Certificates and Approvals - Chain Register		No	
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And Approvals	10.10.05 - Certificates and Approvals - Life raft Certificate		No	
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And Approvals	10.10.06 - Certificates and Approvals - Administration approved LSA, LSS and FFA plans		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.01 - Safety Equipment and Alarms - General Alarm		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.02 - Safety Equipment and Alarms - Fire detection system (Accommodation/E.R/Cargo holds)		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.03 - Safety Equipment and Alarms - Hospital Bell		No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.04 - Safety Equipment and Alarms - Medical locker / equipment		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.05 - Safety Equipment and Alarms - Fridge room alarm		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.06 - Safety Equipment and Alarms - E/R Bilge High level alarms		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.07 - Safety Equipment and Alarms - CO2 / Halon release alarm		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.08 - Safety Equipment and Alarms - Vent fans flaps / funnel flaps / Remote closing flaps		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.09 - Safety Equipment and Alarms - Fixed foam system		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.10 - Safety Equipment and Alarms - Portable foam system	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.11 - Safety Equipment and Alarms - Steam smothering		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.12 - Safety Equipment and Alarms - Inert gas system		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.13 - Safety Equipment and Alarms - Sprinkler system		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.14 - Safety Equipment and Alarms - Fire mains / hydrants	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.15 - Safety Equipment and Alarms - Hoses / nozzles	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.16 - Safety Equipment and Alarms - Pollution Locker and equipments	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.17 - Safety Equipment and Alarms - Emergency fire pump		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.18 - Safety Equipment and Alarms - Emergency generator		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.19 - Safety Equipment and Alarms - Emergency lights		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.20 - Safety Equipment and Alarms - Life boat operation		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.21 - Safety Equipment and Alarms - Life boat equipment		No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.22 - Safety Equipment and Alarms - Life boat engines		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.23 - Safety Equipment and Alarms - Extinguishers - Foam, Water, DCP, CO2	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.24 - Safety Equipment and Alarms - Tankscope, Explosimeter, O2 analyzer and Toxic gas detector		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.25 - Safety Equipment and Alarms - Breathalyzer		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.26 - Safety Equipment and Alarms - CABA, Resuscitation equipment	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.27 - Safety Equipment and Alarms - Fireman's outfit with accessories		No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.28 - Safety Equipment and Alarms - Emergency Towing System	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.12 - Part XII - Environmental	10.12.01 - Environmental - Ballast water management		No	
01.00 - Area/Item Inspected	01.12 - Part XII - Environmental	10.12.02 - Environmental - Garbage management		No	
01.00 - Area/Item Inspected	01.12 - Part XII - Environmental	10.12.03 - Environmental - Ship Energy efficiency plan		No	
01.00 - Area/Item Inspected	01.12 - Part XII - Environmental	10.12.04 - Environmental - Safety Meeting conducted with entire crew by Superintendent	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.01 - Security - Ship Security Records		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.02 - Security - Security Equipments		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.03 - Security - Security Communications and SSAS		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.04 - Security - Vessel Hardening		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.05 - Security - Security Charts, Publications and Guidance		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.06 - Security - Cyber Security incl. Access to IT/OT Terminals, Workstation Security etc.		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.07 - Security - Cyber Response Plan		No	



Maritec Tanker Management Private Limited

Vessel - Bitu Atlantic (IMO: 9382085)

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.08 - Security - Personal Devices usage		No	